

Product Specifications

Item #GP101TA



ROC®

Magid® ROC® GP101TA Ultra-Thin Foam Nitrile
Palm Coated Tear-Away Work Glove – ANSI Cut
Level A1 (solid knit portion ONLY)

PRODUCT DESCRIPTION	
Product Classification	General Purpose Work Glove – Coated
Construction/Design	15-gauge, tear-away seamless machine knit nylon shell
Composition	Nylon shell; foam nitrile palm coating
Color(s)	Black
Size(s)	6 – 12
Cuff/Finish	Color-coded elasticized overcast: grey (6), blue (7), green (8), red (9), black (10), orange (11), white (12)
Unit of Measure	Dozen
Packaging	1 dozen pairs per inner pack; 12 dozen per case

FEATURES & BENEFITS	
• Tear-away 15-gauge nylon shell protects the wearer from the risk of entanglement in rotating tools • Flexible foam nitrile palm coating ensures solid grip of small parts even in wet/oily conditions • High-density nylon shell adds tactile sensitivity, stretch and breathability • Dark color hides dirt and grime to extend wear • Silicone-free, low-lint construction minimizes product contamination • Color-coded overcast for easy sorting and dispensing • ANSI Level A1 Cut Resistance (solid knit portion ONLY, does NOT apply to tear-away points)	

APPLICATIONS	
Assembly, shipping and receiving, material handling, metal fabrication and general maintenance.	

AVAILABLE STYLES							
Size	6	7	8	9	10	11	12
Part Number	GP101TA6	GP101TA7	GP101TA8	GP101TA9	GP101TA10	GP101TA11	GP101TA12

FUNCTIONAL PERFORMANCE		
US Standard: ANSI/ISEA 105 American National Standard for Hand Protection Selection Criteria		
Test Method	Clause	ANSI Level
ASTM F2992 Cut Resistance (SOLID KNIT PORTION ONLY)	-	A1
SERVICE LIFE		
The service life of this product will vary depending on the application and type of care administered. This product should be replaced immediately once a critical or major defect as defined below is noted.		
Critical Defects	Holes/tears	
Major Defects	Dimensional or weight nonconformance, discoloration, other fabric defects	
LAUNDERING GUIDELINES		
Machine wash in warm water (not to exceed 104° F or 40° C) using a mild commercial soap or detergent. Rinse in cold water, and air dry or tumble dry with a low temperature setting (not to exceed 104° F or 40° C).		

Originator	Scott Daigle	Date	9/26/2022		
Revised By	Kim Schultz	Date	3/10/2025	Revision #	3